

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT:

Fuel Spill

DATE OCCURRED 03-26-98

DATE REPORTED

TIME OCCURRED 1300

TIME REPORTED

LOCATION(S) OF OCCURRENCE:

Galvin Fuel Farm

REPORTED BY:

PHONE NO(S):

Galvin Aviation

SUMMARY:

Galvin reported a large fuel spill at the north fuel farm. Officer Sawyer responded with FD#2 and Sgt. Reed in A-54. Pierre from Aeroflight said the deadman switch stuck while he was fueling one of Aeroflight's truck. Aeroflight personell responded with cleanup pads and absorbants. They cleaned up the surface and took the absorbants with them for disposal. The sump tank fuel separator does need to be pumped out at the aircraft fuel farm. The fuel farm owner was advised.

OFFICERS:**ACTION:**